

Applicants : Philip J. Quenzi and Richard W. Jenney
Serial No. : 10/796,619
Page : 4

Remarks:

Upon review of the formal drawings for this application, it was discovered that the reference number 82 was used to refer to the actuator and to the linkage or connecting member. The specification has been amended to change the reference number 82 for the linkage to reference number 85, in order to correct this error. The drawings have also been amended accordingly. Attached are new formal drawings for this application, with this change made in Figures 1, 4, 8, 9, 19, 22 and 27. Also attached are marked up versions of Figures 1, 4, 8, 9, 19, 22 and 27, showing the change to the reference numbers. The drawing and specification amendments are fully supported in the specification and drawings as originally filed. No new matter has been added.


Entry and approval of the new formal drawings and an early and favorable action on the merits is respectfully requested.

Respectfully submitted,

PHILIP J. QUENZI ET AL.


By: Van Dyke, Gardner, Linn & Burkhart, LLP



Date: May 19, 2005



Timothy A. Flory, Registration No. 42 540
2851 Charlevoix Drive, S.E., Suite 207
P.O. Box 888695
Grand Rapids, Michigan 49588-8695
(616) 975-5500

TAF:slg
Enclosures








FIG. 8






FIG. 9








FIG. 27